

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	4-5-2	2013							1
PROPERTY ADDRESS:	4309 Stonebrook						847 TAT /	H.219-8909	
PROPERTY OWNER:	JoAnna Grymes								w- 680-8430
OCCUPIED: YES xx	NO								
					NID I'E	ON		NOTES &	COMMENTS
BUILDING ELEMENT				hru 5 CC	וועמו	ION		NOTES	COMMENTS
		VE					VERY GOOD		
Foundation							5	Slab	
Front Porch								N/A	
Exterior Doors and Windows		1						Windows broke/ d	
Roof Underlay				2					for varments going
•								in/out	11 11
Roof Surface				2					s approx. 11 yrs old
Chimney								N/A	'1 11
Siding				2					sonite rotten on rest of
								house	
Facia and Trim				2	2			Rotten falling off	
Interior Doors					3			fair Holes in sheetrock	,
Interior Walls				2					
Ceilings			1				5	Falling in	
Flooring Underlay				2			3	slab	
Flooring Surfaces				2		1		Old carpet	code but needs to be
Electrical					1	4		checked	
Heating						4		Appears to be in checked	code but needs to be
Plumbing						4		Appears to be in c	code but needs to be
		-							
In my opinion, this structure		is	XX	is not	Suit	able for	human h	nabitation.	
In my opinion this structure	XX	is		is not	Phy	sically 1	feasible f	or rehabilitation.	
In my opinion, this structure	XX	is		is not	Eco	nomica	lly feasib	le for rehabilitation.	
In my opinion, this structure	XX	is		is not	A p	ublic sa	fety haza	rd and should be con	ndemned immediately.
Due to nature of house and sa	afety,	heat	lh an	d welfar	e issue	es as we	ell as fire	hazards with-in stru	cture needs to abated or
repaird immediately.									
EM	IERG	EN	CY A	CTION	IS W	ARRA	NTED:	YES xx NO	

end How		
erry Adams, Certified Building Inspector	Craig Davenport, Fire Marshal	Other Signature