

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	4-14	-2014								
PROPERTY ADDRESS:	410	Ridgecrest Cir.								
PROPERTY OWNER:		Black								
TROPERT OWNER.	Cit	Diack								
OCCUPIED: YES xx	NO									
BUILDING ELEMENT		1	thru 5 (CONDIT	ION		NOTES & COMMENTS			
		VERY POOR				VERY				
Foundation Type:		POOR	2			GOOD	Cracked and giving way from structure			
Piers							Cracked and giving way from structure			
Solid										
Slab										
Front Porch Type:		1					Rotten front and back roof falling in			
Wood										
Concrete										
Exterior Doors and Windows			2				Fair condition sills rotted in places			
Type:										
Wood										
Vinyl										
Aluminum										
Roof Underlay Type:			2				Rotten in places			
OSB										
1x6										
metal										
Roof Surface Type:		1					Rotten dilapidated approx. 12-14 years			
3-Tab Shingles										
Dimensional Shingles	-						27/4			
Chimney			2				N/A			
Siding Type:			2				Shows signs of deterioation			
Wood Lap Vinyl										
Masonite										
Aluminum										
Fascia and Trim Type	-		2				Rotten			
Wood			-				Rottoll			
Vinyl Coil										
Interior Doors Type:			2				Will not close and work proper due to			
Hollow Wood							floor sagging			
Solid Wood										

*											
Interior Walls Type				2	1			Cr	ack	ted and Busted	
Wood Frame											
Metal Frame											
Sheetrock											
Stucco											
Ceilings Type:				2				Cr	ack	red and Busted	
Sheetrock									uon	and Busica	
Stucco											
Ceiling Tile											
Flooring Underlay Type:				2				Sh	ow	s signs of deteriation	
1x6 center match										s signs of deterration	
OSB							7.				
Plywood						-	7,				
Flooring Surfaces Type:			1					Ro	otte	n and Dilapidated	
Carpet								110	, , , ,	i una Briapiantea	
Linoleum											
Hard Wood											
Vinyl											
Electrical		1						No	ot to	Code many issues	
Heating			1					Code many issues			
Plumbing		1				Not to Code many					
In my opinion, this structure		is	XX	is not	Suitable for human habitation.						
In my opinion this structure		is	XX	is not	Physically feasible for rehabilitation.						
In my opinion, this structure	П	is	XX	is not	Economically feasible for rehabilitation.						
In my opinion, this structure											
	XX	is		is not	A pu	blic sai	ety nazaro	an	d si	nould be condemned immediately.	
Due to safety, health and welfare this structure needs to be abated EMERGENCY ACTION IS WARRANTED: YES xx NO											
ENI	LKG	LIN	CYA	CHON	15 W	AKKA	NIED: L	Y	ES	xx NO	
To I M		+									
Terry Adams, Certified Building Inspe			.	Crai	g Davenport, Fire Marshal			ī	+	Other Signature	
,			5	.,,			H	other signature			
		201									
Municipal Buil	ding,	300	South	Church .	Jonesbo	ro, Ar./	Phone 870-	336-	719	4/ Fax 870-336-1358	