

## DEPARTMENT OF PLANNING, INSPECTION AND CODE ENFORCEMENT

## RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION: $10-30-08$							
PROPERTY ADDRESS:	18	09	ArcH	12.	10 at 10		
PROPERTY OWNER: Jue Perkins							
OCCUPIED: YES X	NO						
BUILDING ELEMENT			CON	DITIO	ON		NOTES & COMMENTS
		VERY POOR				VERY GOOD	
Foundation	-	1	2	(3)	4	5	BIK MOSTAN FAILING
Front Porch		1	2	3	4	5	concrete
Exterior Doors and Windows		$\Omega$	2	3	4	5	Broke & Rotter
Roof Underlay		D	2	3	4	5	WEATHER & & ROTTEN
Roof Surface		0	2	3	4	5	:0.3.11
Chimney		1	(2)	3	4	5	FAILING MOSTAN JOINS
Siding		1	2	3	4	5	wood LAC ROTTEN
Facia and Trim		1	$\frac{\circ}{2}$	_3	4-		NA
Interior Doors		1	2	3	4	5	BURNT
Interior Walls			2	3 -	4	5	
Ceilings		1	2	3	4	5	BURNIT OUT
Flooring Underlay		1	2	3	4	5	
Flooring Surfaces			2	3	4	5	
Electrical		1	2	3	4	5	
Heating		1	2	3	4	5	V
Plumbing		1	2	3	4	5	Α
In my opinion, this structure		is 🔯	is not	suitable for human habitation.			
In my opinion this structure		is 🛛	is not	physically feasible for rehabilitation.			
In my opinion, this structure		is 🗵	is not	economically feasible for rehabilitation.			
In my opinion, this structure	X	is	is not	a public safety hazard and should be condemned.			
EMERGENCY CONDEMNATION IS WARRANTED: YES NO							
In my opinion, this structure	$\Box$	is 🗌	is not				d and should be condemned immediately.
Jan S. Ala				•			
Terry Adams, Certified Building Inspector				Craig Davenport, Fire Marshal			al Other Signature