

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	5-19	-19-2014					
PROPERTY ADDRESS: 1116		Burke	Burke				
PROPERTY OWNER: Gab		ina Lopez					
		•					
OCCUPIED: YES xx	NO						
BUILDING ELEMENT		1	thru 5 C	ONDIT	ION		NOTES & COMMENTS
		VERY POOR				VERY GOOD	
Foundation Type:		1				GOOD	Piers starting to fall out
Piers							
Solid							
Slab							
Front Porch Type:		1					Concrete breaking in over whole porch
Wood							
Concrete							
Exterior Doors and Windows			2				Rotten doors, windows fair
Type:							
Wood							
Vinyl							
Aluminum							
Roof Underlay Type:				3			Fair condition
OSB/ Plywood							
1x6							
metal				3			D. I.
Roof Surface Type:				3			Fair condition
3-Tab Shingles Dimensional Shingles							
Dimensional Shingles Chimney					-		N/A
Siding Type: Stucco		1			-		
Wood Lap							Put over rotten woord starting to fall off
Vinyl							
Masonite							
Aluminum							
Fascia and Trim Type			2				Fair suspect of rotten strucute at window
Wood							sills and headers
Vinyl Coil							
Interior Doors Type:		1				-	Rotten and dilapidated
Hollow Wood							*
Solid Wood							

3										
Interior Walls Type			1		Rotten and dilapidated major termite					
Wood Frame					damage					
Metal Frame										
Sheetrock										
Stucco										
Ceilings Type:			1		Falling in					
Sheetrock										
Stucco										
Ceiling Tile										
Flooring Underlay Type:		1			Rotten					
1x6 center match										
OSB										
Plywood										
Flooring Surfaces Type:	Flooring Surfaces Type:				Rotten and non-existing					
Carpet										
Linoleum										
Hard Wood										
Vinyl										
Electrical			1		Not to code					
Heating	1		1		Not to code					
Plumbing			1		Not to code					
In my opinion, this structure		is	XX	is not	Suitable for human habitation.					
In my opinion this structure		is	XX	is not	Physically feasible for rehabilitation.					
In my opinion, this structure		is	XX	is not	Economically feasible for rehabilitation.					
In my opinion, this structure	XX	is		is not	A public safety hazard and should be condemned immediately.					
Due to health, safety and welfare this structure needs to be abated										
		_			IS WARRANTED: YES xx NO					
				CHOIL	IS WINDER LIES AATTO					
Ten AA		1								
Terry Adams, Certified Building Inspector				Craig	Davenport, Fire Marshal Other Signature					
		+								
Municipal Ru	ilding	300	South	Church 1	onesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358					
	- Julie	, 500	Jour	. Just of t	20000000, 121 # 1 HORE 0 / 0 - 250 - / 1 / 7/ 1 AX 0 / 0 - 250 - 1 250					