

DEPARTMENT OF PLANNING, INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	8-	15-08			•n		
PROPERTY ADDRESS:	102	9 He	rpe s	-			
PROPERTY OWNER:	/ -	1 //-					
ROPERTI OWNER.							
OCCUPIED: YES	ON [
BUILDING ELEMENT			CO	NDITI	ON		NOTES & COMMENTS
		VERY				VERY	
Foundation	-	POOR	6)	2		GOOD	
Front Porch		1	2)	3	4	5	Pier
Exterior Doors and Windows		1	2	3	4	5	2 1/1 1 2 2 1/2 2 28
Roof Underlay			2	3	4	5	Broken & FAIIT OFF
Roof Surface			2 2	3	4	5	House Burn out deck weak
Chimney		1	2	3	4	5	*
Siding		1	2	3	4 4	5	meites
Facia and Trim			2	3	4	5 5	Burn'T & CHANCORNOL
Interior Doors		1		3	4	5	DUPN 1 & CHAP. CONCOL
Interior Walls		(2	3	4	5	Quest d FAlling 1.
Ceilings			2	3	4	5	11 11 11 11
Flooring Underlay		999998	2	3	4	5	Floor collasping
Flooring Surfaces		(I)	2	3	4	5	1 1001 Och Hisping
Electrical			2	3	4	5	All destroyed by five
Heating		Ď	2	3	4	5	11
Plumbing		D	2	3	4	5	· · · · · · · · · · · · · · · · · · ·
In my opinion, this structure		is 🔀	is not	suitable for human habitation.			
In my opinion this structure		is 🔀	is not	physically feasible for rehabilitation.			
In my opinion, this structure		is X	is not	economically feasible for rehabilitation.			
		. ~ ~ ~					
EMERGENCY CONDEMNATION IS WARRANTED: X YES NO							
In my opinion, this structure	X	is	is not	a pu	one safe	ty hazar	d and should be condemned immediately.
1 1 11							
Test Han							
Terry Adams, Certified Building	Crai	g Dave	nport, Fi	re Marsh	al Other Signature		