

DEPARTMENT OF PLANNING, INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	7-26-08					*
PROPERTY ADDRESS:	809 monroe					* * * * * * * * * * * * * * * * * * * *
PROPERTY OWNER:	Hobert	Brocke 11				
OCCUPIED: YES I	NO					
BUILDING ELEMENT		CONDITION		80	NOTES & COMMENTS	
v	VERY				VERY	
Foundation	POOR 1	2	(2)	1	GOOD 5	FAIR condition
Front Porch	1	2	3	(A)	5	concrete
Exterior Doors and Windows		2	3	(4)	5	Broket BurnT OUT
Roof Underlay	1	2	3	4	5	Bugant & CHame I
Roof Surface	1	2	(3)	4	5	FAIR condition
Chimney	\bigcirc	2	3	4	5	FAILING + coming house
Siding	$\frac{C}{1}$	2	3	4	. 5	FAIR DUT ON SIATE
Facia and Trim	D	2	3	4	5	Burn't
Interior Doors	$\widetilde{\mathbb{A}}$	2	3	4	5	• 11
Interior Walls		2	3	4	5	11
Ceilings	1	2	3	4	5	h ·
Flooring Underlay	1	2	3	4	5	ROTTED & FAILING THOU
Flooring Surfaces	D	2	3	4	5	does not EXIST
Electrical	0	2	3	4	5	All damaged From Fire
Heating		2	3	4	5	" " " " " " " " " " " " " " " " " " " "
Plumbing	(1)	2	3	4	5	11 11 11
In my opinion, this structure [is 🗓	is not	suitable for human habitation.			
In my opinion this structure	is X	is not	physically feasible for rehabilitation.			
In my opinion, this structure	∐ is ⊠	is not	economically feasible for rehabilitation.			
EMERGENCY CONDEMNATION IS WARRANTED: YES NO						
In my opinion, this structure is is not a public safety hazard and should be condemned immediately.						
Tong & Ach						
Terry Adams, Certified Building Inspector Craig Davenport, Fire Marshal Other Signature						