

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	8-28-15				
PROPERTY ADDRESS:	3704 GRIFFIN				
PROPERTY OWNER:	SHEVIE HADL	GEORGE TOLL	ISON		
OCCUPIED: YES NO Y	ΧX				
BUILDING ELEMENT	1 thru 5	CONDITION	NOTES & COMMENTS		
	VERY		VERY		
	POOR		GOOD		
Foundation Type:	1			HOUSE IS COMPLETELY	
Piers				DESTROYED BY FIRE AND WATER	
Solid				DAMAGE	
Slab					
Front Porch Type:	1			HOUSE IS COMPLETELY	
Wood				DESTROYED BY FIRE AND WATER	
Concrete				DAMAGE	
Exterior Doors and Windows	1			HOUSE IS COMPLETELY	
Type:				DESTROYED BY FIRE AND WATER	
Wood				DAMAGE	
Vinyl					
Aluminum					
Roof Underlay Type:	1			HOUSE IS COMPLETELY	
OSB/ Plywood				DESTROYED BY FIRE AND WATER	
1x6				DAMAGE	
metal					
Roof Surface Type: Metal	1			HOUSE IS COMPLETELY	
3-Tab Shingles				DESTROYED BY FIRE AND WATER	
Dimensional Shingles				DAMAGE	
Chimney					
Siding Type:	1			HOUSE IS COMPLETELY	
Wood Lap				DESTROYED BY FIRE AND WATER	
Vinyl				DAMAGE	
Masonite					
Aluminum					
Fascia and Trim Type	1				
Wood					
Vinyl Coil					
Interior Doors Type:					
Hollow Wood					
Solid Wood					

Interior Walls Type			1					HOU	SE IS COMPLETELY		
Wood Frame									TROYED BY FIRE AND WATER		
Metal Frame			ļ					DAM			
Sheetrock											
Stucco											
Ceilings Type:			1					HOU	SE IS COMPLETELY		
Sheetrock			ļ						TROYED BY FIRE AND WATER		
Stucco								DAM			
Ceiling Tile											
Flooring Underlay Type:			1					HOU	SE IS COMPLETELY		
1x6 center match								DEST	TROYED BY FIRE AND WATER		
OSB								DAM	AGE		
Plywood											
Flooring Surfaces Type:			1								
Carpet								HOU	SE IS COMPLETELY		
Linoleum									TROYED BY FIRE AND WATER		
Hard Wood			ļ					DAM	IAGE		
Vinyl											
Electrical			1						TROYED		
Heating		1						DEST	TROYED		
Plumbing		1				DESTROYED		TROYED			
In my opinion, this structure		is	X	is not	Suitable for human habitation.						
In my opinion this structure		is	X	is not	Physically feasible for rehabilitation.						
In my opinion, this structure		is	X	is not	Economically feasible for rehabilitation.						
In my opinion, this structure	X	is		is not	A public safety hazard and should be condemned immediately.						
EMERGENCY ACTION IS WARRANTED: YES XX NO											
			\neg						T		
Tim Renshaw, Chief Building I	Inspe	ctor	-						Other Signature		
Other Signature									Other Digitalia		
Jana Ferral											
16 18	Municipal Building 200 South Chunch Ispaghana An / Blanc 970 227 7104/ Ear 970 227 1259										
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358											