

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	12-3	-2013										
PROPERTY ADDRESS:	3611	611 ½ School St.										
PROPERTY OWNER:	Flor	rence A. Jones										
OCCUPIED: YES XX N	Ю											
BUILDING ELEMENT		1	thru 5 C	CONDIT	ION		NOTES & COMMENTS					
		VERY	;			VERY						
Foundation Type:		POOR 1				GOOD	Completely Dilacited 1					
Piers		1					Completely Dilapidated					
Solid				, o r								
Slab												
Front Porch Type:		1					Completely Dilapidated					
Wood				7			Somptotoly Bhaplauteu					
Concrete												
Exterior Doors and Windows	S	1					Completely Dilapidated					
Type												
Wood												
Vinyl												
Aluminum												
Roof Underlay Type: 2x4		1					Completely Dilapidated					
OSB												
1x6				142,00								
metal												
Roof Surface Type: Metal		1					Completely Dilapidated					
3-Tab Shingles			2									
Dimensional Shingles												
Chimney		1					Completely Dilapidated					
Siding Type:		1					Completely Dilapidated					
Wood Lap												
Vinyl												
Masonite Aluminum												
		1										
Fascia and Trim Type Wood		1					Completely Dilapidated					
Vinyl Coil												
Interior Doors Type:		1					Completed Direction					
Hollow Wood		1					Completely Dilapidated					
TIOHOW WOOD												

Solid Wood		T				I		T	-			
Interior Walls Type			1					C	omr	eletely Dilapidated		
Wood Frame									r	and a supration		
Metal Frame												
Sheetrock												
Stucco												
Ceilings Type:			1					Co	omr	letely Dilapidated		
Sheetrock									1			
Stucco												
Ceiling Tile												
Flooring Underlay Type:			1					Co	omp	letely Dilapidated		
1x6 center match									•			
OSB						4,						
Plywood												
Flooring Surfaces Type:			1					Co	omp	letely Dilapidated		
Carpet												
Linoleum												
Hard Wood												
Vinyl												
Electrical			1					No	ot to	code		
Heating		1				Not to code		code				
lumbing		1				Not to code		code				
In my opinion, this		is	XX	is not	Suitable for human habitation.							
structure		_										
In my opinion this		is	XX	is not	Physically feasible for rehabilitation.							
structure												
In my opinion, this		is		innet	F							
structure		18	XX	is not	Economically feasible for rehabilitation.							
Structure												
In my opinion, this	XX	is		is not	A public safety hazard and should be condemned							
structure					immediately.							
Due to safety, health and we								med	liate	ly		
EM	ERG	EN	CY A	CTION	IS W	ARRA	NTED:	Y	ES	xx NO		
Tem of for												
Terry Adams, Certified Building Inspe			-	Craig Davenport, Fire Marshal						Other Signature		
		+	_						++			
		+							++			
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358												