

## DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

## RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	4/1/15									
PROPERTY ADDRESS:	728 W Huntington Wells Fargo Home Mortgage									
PROPERTY OWNER:										
OCCUPIED: YES NO	XX	,								
				NOTES A COMMENTS						
BUILDING ELEMENT		ru 5 CONDIT		NOTES & COMMENTS						
	VERY POOR		VERY GOOD							
Foundation Type: Piers Solid Slab		4		Very bad shape, falling in at several different rooms						
Front Porch Type: Wood Concrete		4		Needs removed with rest of house						
Exterior Doors and Windows Type: Wood Vinyl Aluminum		3		Some wood some vinyl, needs to be removed with house						
Roof Underlay Type: OSB/ Plwood 1x6 metal		3		Decent shape, not bad for the condition of rest of house						
Roof Surface Type: Metal 3-Tab Shingles Dimensional Shingles		3		Decent						
Chimney Siding Type: Wood Lap Vinyl Masonite Aluminum		3		Out side looks good, not bad for the condition of rest of house						
Fascia and Trim Type Wood Vinyl Coil		3		Out side looks good, not bad for the condition of rest of house						
Interior Doors Type: Hollow Wood Solid Wood		3		Old needs replaced						

Interior Walls Type	***************************************				***************************************	orania managaran	T	Holes in walls, needs replaced	
Wood Frame		na n		4				,	
Metal Frame		onenene principal de la constantida de							
Sheetrock		nos spenios de la constanción							
Stucco		-	- I			-	*		
Ceilings Type:					3			Needs repaired or replaced	
Sheetrock							Designation		
Stucco	7			-					
Ceiling Tile								•	
Flooring Underlay Type:								Very bad shape, holes in floors and	
1x6 center match				4				unlevel	
OSB	,	- Second Control of Co		Promotor of the Control of the Contr			*ADDITION OF THE PROPERTY OF T		
Plywood				Vertical					
Flooring Surfaces Type:								Needs replaced	
Carpet				4			**************************************		
Linoleum	1	-		***************************************			Avenuencen		
Hard Wood		-					-nananananan		
Vinyl				-		1			
Electrical				4				Not to code	
Heating	-			4				Not to code	
Plumbing	1			4				Not to code	
						1			
		1							
In my opinion, this structure		is	XX	is not	Suitable for human habitation.				
In my opinion this structure		is	XX	is not	Physically feasible for rehabilitation.				
In my opinion, this structure		is	XX	is not	Economically feasible for rehabilitation.				
In my opinion, this structure	XX	is		is not	A public safety hazard and should be condemned immediately.				
E	MER	GEN	NCY A	CTION	IS W	VARRA	NTED:	YES NOXX	
						-			
Tim Renshaw, Chief Building	g Inspec	ctor						Other Signature	
2-11	1/11	1.							
Jam Arthur 7	44	113	3		***************************************				
Municipal B	nilding	300	South (	Church Je	nacho	no Ar/I	Phone 870	-336-7194/ Fax 870-336-1358	