

<u>AFFIDAVIT</u>
Alisa Hamilton & Ronnie Stanback
40 Jacqueline Stanback
2109 Sweet Gum Dr.
Jonesboro, AR 72401
RE: 123 Miller Ave Janesborg, AR 72401
I, Michael McQuay, a Code Enforcement Officer, being duly sworn upon oath, that I served the
attached notice(s) upon each of the persons or firms therein addressed, by depositing copies
thereof in the United States Mail, enclosed within envelopes plainly addressed, as shown with
postage fully prepaid, at the Jonesboro, Arkansas Post Office located at 310 East Street, Suite A. before 3:00 P.M., on the
Michael McQuay
Jonesboro Code Enforcement
Subscribed and sworn to before me the 6th day of Oecember, 2022.
Notary Public  Notary Public

My commission expires: May 20, 2032



Notice of Violation

Date: 12/05/2022

ALISA HAMILTON RONNIE STANBACK C/O JACQUELINE STANBACK 2109 SWEET GUM DR JONESBORO, AR 72401

SUBJECT: 223 MILLER AVE JONESBORO, AR 72401

According to county records, you are the owner of the subject property. Please be advised that the structure on this property has been inspected by the City Building and Code Enforcement inspectors and has been found to be unfit for human habitation by virtue of its dilapidated and unsanitary condition. This property poses a hazard to the public and is a nuisance against public health.

Within 10 (ten) calendar days from the date of this letter you are required to respond to this notice in writing, indicating you intention to either repair, re-inhabit, or raze and remove this structure. Should you choose to repair or rehab the structure, you will have to obtain a building permit and start work within 40 calendar days from the date of this notice. The building permit will be issued for a total of 45 calendar days at which time the repair or rehab work must be complete and able to pass all building, electrical, plumbing, and mechanical inspections.

If you decide to raze and remove this structure, removal and clean-up activities must be completed within 40 days of this notice.

If you decide not to repair or remove this structure, it will be necessary for the City Council to consider condemning the structure to ensure the repair, rehab, securing, and/or razing and removal of this nuisance. All costs involved in the condemnation process would be charged to you. Collection would be actively pursued.

We look forward to your cooperation in this matter. If you have any questions, call our office at (870)933-4658.

Sincerely,

David Cooley Code Enforcement Officer P.O. Box 1845 Jonesboro, AR 72403

CE20-8573

Sign if served in person

Code Enforcement Officer Signature, if delivered in person

Property Owner/Interested Party Signature, if delivered in person



## DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

## RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF	<b>DECEMBER 5, 2022</b>			CASE NUMBER: CE20-8573					
INSPECTION:					*				
PROPERTY ADDRESS:	223 I	MILLER							
PROPERTY OWNER:		NIE & J	ACQU]	ELINE	E STA	NBACK			
5-000 (A)	O XX								
BUILDING ELEMENT	ENT 1 thru 5 CONDITION NOTES & COMMENTS								
		VERY POOR				VERY GOOD			
Foundation Type:			2				FOUNDATION IS A	BLOCK PIER	
Piers							WITH CRACKS, MIS		
Solid							THAT NEEDS REPAI	RED	
Slab									
Front Porch Type:			2				WOOD PORCH N	EEDING	
Wood							SOME BOARDS F		
Concrete							HAND RAIL FOR		
Exterior Doors and Window	VS	1					MOST ARE BROK		
Type:							BOARDED. ALL		
Wood							SEVERE SMOKE		
Vinyl							ALL NEED REPL		
Aluminum									
Roof Underlay Type:		1					UNDERLAY WHI	ERE FIRE	
OSB/ Plywood							WAS IS DAMAGE		
1x6							NEEDS REPLACE		
metal							SAGGING.	<i>D</i> . Re of 18	
Roof Surface Type: Metal			2				SHINGLES ARE O	DLD AND	
3-Tab Shingles							DAMAGED. MUS		
Dimensional Shingles							REPLACED		
Chimney							N/A		
Siding Type:		1					VINYL SIDING OVE	R WOOD.	
Wood Lap							MUCH OF THE SIDIN		
Vinyl							REAR, SOUTH, AND		
Masonite							IS HEAVILY DAMAC MISSING FROM THE		
Aluminum							NEEDS REPLACED.	TIRE AND	
Fascia and Trim Type			2				FASICIA AND TR	IM ARE	
Wood							AGING AND NEE		
Vinyl Coil							OR REPLACED		
Interior Doors Type:		1					BROKEN, MISSIN	IG OR	
Hollow Wood							BURNED UP. ALI		
Solid Wood							REPLACED		
Interior Walls Type		1					SHEETROCK WAL	LS WITH	
Wood Frame							HOLES, SMOKE, A		
Metal Frame							DAMAGE THROUG	GHOUT THE	
Sheetrock							HOME. STUDS DAI		
Stucco							FIRE AREA NEED I		
							ALL SHEETROCK	REPLACED	

Ceilings Type:			1					SHEETROCK CEILINGS.	
Sheetrock								HOLES, MISSING, SMOKE	
Stucco								AND WATER DAMAGE	
Ceiling Tile								THROUGHOUT. ALL NEEDS	
								REPLACED	
Flooring Underlay Type:			1					PLYWOOD UNDERLAY HAS	
1x6 center match								SMOKE WATER, AND/OR	
OSB								FIRE DAMAGE. NEEDS	
Plywood								REPAIRED OR REPLACED	
Flooring Surfaces Type:			1					ALL FLOOR COVERING HAS	
Carpet	-JP-							SMOKE AND WATER	
Linoleum								DAMAGE NEEDS REPLACED	
Hard Wood									
Vinyl									
Electrical								NOT TO CODE	
Heating								NOT TO CODE	
Plumbing								NOT TO CODE	
In my opinion, this		is	XX	is not	Suitable for human habitation.				
structure									
In my opinion this		is	XX	is not	Physically feasible for rehabilitation.				
structure						,			
In my opinion, this		is	XX	is not	Fcor	nomica	lly feasik	ale for rehabilitation	
structure		15	AA	13 1101	Economically feasible for rehabilitation.				
					<u>.</u>				
In my opinion, this	XX	is		is not					
structure					immediately.				
	ED ~=		** . ~	TION: 3	N <b>XX</b> 7 7 7	DD : -			
								YES NO XX	
HOME WAS SECURE A	I IIM	E O	FINSI	ECHO	N BU	I WAS	SPREVI	OUSLY NOT SECURE.	
Tim Danchary Chief Daniel	. a I	. at -						Devid Cooley Code F. C	
Tim Renshaw, Chief Building Inspector							_	David Cooley, Code Enforcement	
Jain Lens	5/	-							
								-/-	
			-						
Municinal Ruile	ling 30	0 So	uth Chi	ırch Jone	shoro	Ar/Ph	ne 870-33	36-7194/ Fax 870-336-1358	
Municipal Dune	5, 50	0.500	ath CH	i ch bone	50010,	2 & 1 + / 1 H	one 0/0-3c	70-11741 FAX 010-330-1330	

## U.S. Postal Service<sup>™</sup> CERTIFIED MAIL<sup>®</sup> RECEIPT

54

23

5

435

0000

2720

7021

Domestic Mail Only For delivery information, visit our website at www.usps.com®. Certified Mail Fee Extra Services & Fees (check box, add fee as Return Receipt (hardcopy) Return Receipt (electronic) Postmar Certified Mail Restricted Delivery DEC 05 2022 Adult Signature Required Adult Signature Restricted Delivery \$ Postage **Total Postage and Fees** Sent To Street and Apt. No., or PO Box No. City, State, Zil onesboro, AR

PS Form 3800, April 2015 PSN 7530-02-000-9047

See Reverse for Instructions